



TECH BULLETIN

TECH BULLETIN NUMBER	0165
PCR	111009
DATE	11/10/2009
SUBJECT	MMS output breaker 15A
MODELS AFFECTED	MMS1012 & MMS1012G
REPAIR PROCEDURE	None
WARRANTY	Non-warranty item

OEM request: Changed the 12 amp output switchable circuit breaker to a 15 amp output switchable circuit breaker to allow full branch circuit capacity.