



TECH BULLETIN

TECH BULLETIN NUMBER 0161
PCR 092809

DATE 09/25/09

SUBJECT MMS Power Board rev D new
AUX supply

MODELS AFFECTED MMS1012 & MMS1012G

REPAIR PROCEDURE If serial # is below U1-00585
the inverter must come back
to magnum for repair

WARRANTY Non-warranty item

MMS transformer (35-0016/CTM 27006) now requires ring terminals (1 per lead for a total of 4). Care MUST be taken not to damage power supply inductor when attaching ring terminals. Torque specification is 85% of normal – damage to PCB studs will occur if over tightened.

Was:	Is:	Implication:
MMS Power Board rev C	MMS Power Board rev D	
	New power supply components added to board in place of previous power supply. All compatibility limitations imposed in Tech Bulletin 159 still apply.	