



## TECH BULLETIN

TECH BULLETIN NUMBER	0127
PCR	04172007 MS4024 Control
SUBJECT	5 Watt Search
MODELS AFFECTED	MS4024
REPAIR PROCEDURE	Replace the Control Board
WARRANTY	Standard warranty applies Call for an RMA

This modification was done to improve the accuracy of the search circuit. If there is any question about the operation of the search circuit please call Magnum Technical Support.