



TECH BULLETIN

TECH BULLETIN NUMBER      0124

PCR                                      Oct 25-06 ME-RB SW8.3

SUBJECT                                Firmware update to r8.3

MODELS AFFECTED                ME-RB

REPAIR PROCEDURE                Not Applicable

WARRANTY                            Non-warranty item

Was:	Is:	Implication:
r8.2	r8.3	
Poor contrast on power up	Better contrast on power up	Now, on power up, you can read the display. Contrast can be adjusted in the setup menu
	Added Models: <ul style="list-style-type: none"> <li>• MMS1012</li> <li>• MM1524</li> <li>• MS4448AE</li> </ul>	Remote would report "unknown" if connected to one of these models with the earlier revisions of firmware
	Added Error codes: Stuck relay, No stack clock Internal relay Internal charger	Remote would report "unknown fault" if a fault was reported to an the earlier revisions of firmware
Changed Error Codes: Backfeed Fault Internal Fault-1 Internal Fault-2	Changed to: AC Backfeed Internal Bridge Internal NTC	Clarified faults to make troubleshooting simpler and improve user interface.