



TECH BULLETIN

TECH BULLETIN NUMBER: 0118

DATE: September 9, 2005

Subject: Newmar Only Upgrade

Models affected: ME2012 SERIAL # B1-02800 thru B1-05000

Notification: Owners of record will receive a Newmar notification letter.

Repair Procedure: Units affected had FET Boards manufactured by an outside contractor who did not follow the proper manufacturing process. The FET board was overheated during the soldering process and although the unit may operate properly the FET board may eventually fail due this overheating process.

Field replacement of the FET board should not be attempted. The entire unit should be replaced under warranty exchange with a factory upgraded unit.

Parts Ordering: Contact Customer Service and provide Model and Serial number information in order to obtain a replacement unit.

Warranty: Labor for replacement unit is 1 hour. Replacement unit will be sent at no charge and a return shipping label will be included for return freight charges.

All standard warranty labor rates apply.

Magnum Energy Inc.
Tech Service Dept.