



TECH BULLETIN

TECH BULLETIN NUMBER: 0116

DATE: February 19, 2007

Subject: TV lines

Models affected: ALL

Some reports of "herring bone" lines in TVs have been reported when in a heavy charge mode. The charger can be in Bulk, Absorption or Float but the DC Amps is usually above 60A when any lines first appear.

First action should be to check all coax connections, antenna booster and also check for any bad splitters in the system.

If none of the above problems are found, try installing an in-line filter that is designed to stop RF interference to TV's. A recommended filter is the **Ameco HP-75T** high pass filter - this filter has been found to reduce or eliminate lines in the TV.

This bulletin is for informational purpose only.

Magnum Energy Inc.
Tech Service Dept.