



TECH BULLETIN

| | |
|-----------------------------|---|
| TECH BULLETIN NUMBER PCR | TB110825 |
| DATE | 8/25/2011 |
| SUBJECT | NEWMAR Compatibility |
| MODELS AFFECTED | ME & MS Series |
| REPAIR PROCEDURE | Newmar E-Plex EMS will need to specify firmware v3.7 when replacing Inverter or Control board |
| WARRANTY | Non-warranty item |

Newmar's E-Plex EMS system is only compatible with firmware up to firmware v3.7. Newmar also uses Silver Leaf EMS systems which will work with newer firmware v5.4.

If a Newmar coach need a control board you will need to verify if the coach has E-Plex or Silver Leaf EMS system. If it is an E-Plex system you will need to specify when you order a replacement TCB-MS???? that you need firmware 3.7.