



TECH BULLETIN

TECH BULLETIN NUMBER	0164
PCR	11022009
DATE	11/02/2009
SUBJECT	AGS removal of voltage suppressors
MODELS AFFECTED	ME-AGS (all types)
REPAIR PROCEDURE	None
WARRANTY	Non-warranty item

Remove all static suppression devices from AGS. Static suppression devices could short causing undesired operation of the test button.