



TECH BULLETIN

TECH BULLETIN NUMBER 0145
PCR 013108
SUBJECT AC Board Improvement
(sidactor)
MODELS AFFECTED See Below – Table 1
Warranty Standard warranty is applicable

With this change, the sidactor was removed and the PPTC was moved to the voltage sense transformer for the charger circuit (T5).

Sidactor Removed	Serial Number
MS2812	H1-05686
ME2012	B1-23179
MS2000	T1-02741
MS2012	J1-03096
MS4024AE	X1-00073
MM1012E	Y1-00096
MM1212	M1-01583
MM612	L1-01653
MM1212AE	R1-00232
MS4024	K1-01245
ME2512	C1-01707
ME2000	N1- None
ME3112	D1-01608
RD2824	F1-10171
RD1824	E1-10071
MM612AE	Q1-00310
MS4448AE	V1-00217
MMS1012	U1-00132

Table 1 – Serial Number Breaks