



## TECH BULLETIN

TECH BULLETIN NUMBER	0136
PCR	08132007-MS2000 FET
SUBJECT	MS2000 FET board change
MODELS AFFECTED	MS2000: <ul style="list-style-type: none"><li>• AMS2000-0010</li><li>• AMS2000-0015</li><li>• AMS2000-0020</li></ul>
REPAIR PROCEDURE	Swap FET Board
WARRANTY	Non-warranty item

MS2000 FET board has changed to the small FET board.