



TECH BULLETIN

TECH BULLETIN NUMBER 0131

PCR 06152007 (MS series charger)

SUBJECT MS Series Charger Defaults

MODELS AFFECTED MS2000
 MS2012
 MS2812

REPAIR PROCEDURE Update Control Board

 Call for an RMA

WARRANTY Standard warranty applies

 Please call for an RMA

Was:	Is:	Implication:
v3.3	v3.4	
No charge without remote, shore amps and charge amps both defaulted to 0 amps	Will charge without remote, shore amps and charge amps default to 30 amps and 100% respectively.	Unit will now charge without a remote
EQ for AGM1 15.0V	EQ for AGM1 15.5V	EQ value more appropriate for this profile. No change to the user