



TECH BULLETIN

TECH BULLETIN NUMBER 0130

PCR 05112007 (ME-RC v1.6)

SUBJECT ME-RC update v1.6

MODELS AFFECTED ME-RC

REPAIR PROCEDURE N/A

WARRANTY Non-warranty item

Was:	Is:	Implications:
v1.5	v1.6	
In production test, saved bytes would not always load correctly.	Added a load and compare function to ensure that settings are being loaded correctly.	Ensure that the user's settings are saved in when changed
Add settings:	Added 40 and 60 amp settings to Shore button.	Added functionality to improve the user interface
Add settings:	Added 48-volt LBCO settings for MS4448. Display now only shows settings for voltage that it is connected to. Note: Voltages below 16.0 are 12 volt, over 16.0 are 24 volt, and over 32.0 are for 48 volt settings.	