

TECH BULLETIN

TECH BULLETIN NUMBER TB0149

PCR 042808

SUBJECT

ME-AGS Software Version 4.1

MODELS AFFECTED

ME-AGS, ME-AGS-S, ME-AGS-WB, ME-AGS-WB-S

WARRANTY

Not applicable

Software / Other Description	
WAS:	IS:
ME-AGS V4.0	ME-AGS V4.1
Delay between T1 and T2 was 4 seconds in portable mode.	Delay is now 2 seconds.
Added to portable mode:	2 second delay after Relay 2 (pin 6 and 7), then Relay 3 (pin 1 and 8) closes for 5 seconds. B+ signal is detected after relay 3 opens for 3 seconds
T2 time was 4 Seconds in 3-Wire mode.	T2 time is now 2 seconds.
T3 time was 10 seconds in 3-Wire mode.	T3 time is now closed for 5 seconds.