



TECH BULLETIN

TECH BULLETIN NUMBER 0140

PCR 10252007-MMS1012 SW 1-1

SUBJECT MMS1012 Default Charge Current

MODELS AFFECTED MMS1012

REPAIR PROCEDURE Send a MM-RC or Updated control board

Call for an RMA

WARRANTY Standard warranty applies

Starting Serial Numbers

- U1-00046
- U1-00065
- U1-00061
- U1-00049
- U1-00054
- U1-00075 and greater

Was:	Is:	Implication:
MMS1012 Software version 1.0	MMS1012 Software Version 1.1	
0A charge current without ME/MM remote connected.	100% charge rate without remote connected.	Need a remote or an updated control board Call for an RMA
Default Absorb time 120 Min	Default Absorb time 60min = 200AH battery	Charger will stay in Absorption for 1 hour instead of two