



TECH BULLETIN

TECH BULLETIN NUMBER        0137

PCR                                        08142007-AGS 3.7

SUBJECT                                ME-AGS Update to r3.7

MODELS AFFECTED                ME-AGS

REPAIR PROCEDURE                Update AGS to r3.7

WARRANTY                                Non-warranty item

Call for an RMA - \$50 fee

Was:	Is:	Implication:
v3.6	v3.7	
When AGS is network connected and connected to a v1.5 or newer remote, the AGS did not load the current time off of the network. The AGS would always be in quiet time when "Enable w/QT" is selected.	AGS reads current time off of the network.	If network control of an ME-AGS is desired and a ME-RC with a version 1.5 or higher is being used, the AGS needs to be updated to v3.7
No communication delay was 1 second. If no data is seen from the network for more than 1 seconds, AGS returns back into stand alone mode.	Lengthen no communication delay to 3 seconds. If no data is seen from the network for more than 3 seconds, AGS returns back into stand alone mode.	If communications are interrupted for more than 3 seconds the AGS will default to Stand Alone Mode. If communications are then reestablished the AGS will go into whatever mode it was in the status of the ME-RC will not change.