

TECH BULLETIN

TECH BULLETIN NUMBER 0134

PCR 07262007-ME-MS-RD Gnd Lug

SUBJECT Ground Lug; increase lug size

to be compliant with

regulatory requirements

MODELS AFFECTED All MS, ME, and RD inverters

REPAIR PROCEDURE N/A

WARRANTY Non-warranty item

